

Known compatible Printers to Print Server

>> The Canon Printer <<
Canon I450
Canon I550
Canon I850
Canon I950
Canon I255
Canon I355
Canon I455
Canon I475D
Canon I560
Canon I865
Canon I905D
Canon I6100
Canon I9100
Canon I6500
Canon MP730
Canon PIXUS 990i
Canon S400
Canon S520
Canon S200SPX
Canon BJC-210S
Canon BJC-255SP
Canon BJ-330
Canon BJ F9000
Canon BJC-600, 620
Canon BJC-2000SP
Canon BJC-4100, 4200, 4300, 4500, 4550
Canon BJC-5500T
Canon BJC-6000, 6500
Canon BJC-7000
Canon BJC-8200
Canon LBP-720, 740
>> The Epson Printer/plotter <<
Epson Stylus Photo 670
Epson Stylus Photo 700, 710, 750
Epson Stylus Photo 810, 830, 870
Epson Stylus Photo 1200, 1270
Epson Stylus Photo 2000P, 2100
Epson Stylus Photo EX, EX2, EX3
Epson Stylus Pro XL
Epson Stylus C60
Epson Stylus Color 400, 440, 460, 480
Epson Stylus Color 600, 640, 660
Epson Stylus Color 740

Epson Stylus Color 800, 850, 860
Epson Stylus Color 900
Epson Stylus Color 1160
Epson Stylus Color 1500, 1520
Epson Stylus Color 1900
Epson Stylus Color 3000
Epson Stylus Color 4100
Epson Stylus Pro 9000
Epson CX3100
Epson LQ-100
Epson LQ-300, 300+
Epson LQ-550, 570+
Epson LQ-680
Epson LQ-1000C
Epson LQ-1170C
Epson LQ-2080C
Epson LQ-2170C
Epson LP-8900
Epson EPL-N2000, N2010
Epson EPL-5500, 5700, 5700L, 5800, 5900
Epson EPL-6100
Epson PM 700C
Epson TM T88III
Epson RX510
>> The Fujitsu Printer <<
Fuji 10V, 14V
Fuji DL-700, 900
Fuji DL-3400, 3800
Fuji DL-6400Pro
Fuji Jet Wind 500C
>> The HP Printer/Plotter <<
HP 3535, 7150
HP Series
HP Portable
HP LaserJet III
HP LaserJet 4P, 4L, 4V
HP LaserJet 5L
HP LaserJet 6P, 6L
HP LaserJet 1100, 1100A
HP LaserJet 1500L
HP LaserJet 2100, 2100M
HP LaserJet 2200D
HP LaserJet 2300
HP LaserJet 2550L
HP LaserJet 3030
HP LaserJet 3330

HP LaserJet 4000
HP LaserColorJet 8500
HP DeskJet 400, 420
HP DeskJet 500, 550C, 560C
HP DeskJet 670, 670C, 680C
HP DeskJet 720C
HP DeskJet 810C, 845C, 890C
HP DeskJet 930C, 950C, 970CXI
HP DeskJet 1120C, 1125C, 1180C, 1220C
HP DeskJet 1180C→PCL 3
HP DesignJet 350C
HP DesignJet 500C
HP DesignJet 600C
HP LaserJet 3330
HP LaserJet 4000
HP LaserJet 5000, 5550, 5652
HP LaserJet 1200C→PCL 5e/6
HP LaserJet 1320C→PCL 6
HP OfficeJet T45, 710, K80
HP Photosmart P1000
>> The IBM Printer <<
IBM 5577
IBM 4039 16L
IBM Infor Printer 20
IBM InfoPrint 20, 32
IBM InfoPrint 1332, 1412
>> The Lexmark Printer <<
Lexmark 4039 10R
Lexmark 5700
Lexmark Z11
Lexmark Z43, Z45, Z52, Z55
Lexmark Z515
Lexmark Z605, Z705
Lexmark Z818
Lexmark Optra Color 45
Lexmark Optra C710, C720, C750
Lexmark Optra E, E+, E210, E310, E322
Lexmark Optra K1220
Lexmark Optra M410, M412
Lexmark Optra N
Lexmark Optra P707, P3150, P6250
Lexmark Optra R+
Lexmark Optra S1250, S1855
Lexmark Optra SC-1275
Lexmark Optra SE-3455
Lexmark Optra T420, T614, T620
Lexmark Optra W810, W812

Lexmark Optra X1150, X2250, X5150, X6150
>> The NEC Printer <<
NEC P2200
NEC P3200
NEC P5300
NEC P6300
NEC P7300
NEC P8000C
>> The Panasonic Printer <<
Panasonic 2023
Panasonic KX-P1121
Panasonic KX-P1624
Panasonic KX-P6500
Panasonic KX-P8415
>> Other Printers <<
Brother HL-1260
CD T120
Citizen GSX-230
Futek 84+
Kyocera 1920
Kyocera FS-1000, 1010, 1020
OKI ML-391
OKI B4350
OKIdata OL-400
Olivetti JP450
Minolta Di350
Minolta Pageworks 1100
Printtec PR856C
Star NX-2420
Tektronix Phaser 350
Xerox Phaser 3310
Samsung ML-1710
Samsung ML-1750
Samsung SRP 270
Samsung SCX-4016

Known Incompatible Printers to Print Server

No.	Printer Model
1	ALPS AlpsLSX-1600 →GDI
2	Canon BJC 610, 620 →GDI

3	Canon BJC 5100, 5000 →GDI
4	Canon FAX L350 →GDI
5	Canon LBP 430W/660/800/810/1210 →GDI
6	Citizen NoteBOOKII/PN48 →GDI
7	Epson 5700L/5800L/5900L/6100L
8	Epson AcuLaser C900/C1000
9	Epson LQ 300K/K+
10	Epson Stylus Photo 825/915
11	Epson Stylus Scan 2000/2500 →Multifunction and All-in-one
12	HP Deskjet 3325
13	HP LaserJet 1000/1005 →Special USB cable
14	Lexmark ColorJet Print 2050 →GDI
15	Lexmark C750
16	Olivetti PG304 →GDI
17	OKI Page 8W →GDI
18	Panasonic KXP7100 → (GDI printer)
19	Samsung ML-1210 → (GDI printer)
20	HP psc1315 (LIDIL protocol GDI printer)

Note:

1. The print server cannot support all GDI printers this is architecture limitation.
2. Under Mac OS, the print server can only support Postscript printers because of MAC OS printing language protocols.
3. The print server may not work with MFP (Multi Function Printer) because it's more PC interactive design and cannot used from network.